

Oil Field Environmental Incident Summary

Incident: 20150102134544 **Date/Time of Notice:** 01/02/2015 13:45

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: JONSRUD 151-96-4A-10-1HS

Field Name: CLEAR CREEK

Well File #: 27654

Date Incident: 1/2/2015

Time Incident: 01:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 96

Sec: 4

Qtr:

Location Description:

Submitted By: Derek Enderud

Received By:

Contact Person: Derek Enderud
PO BOX 935
BISMARCK, ND 58502

General Land Use: Cultivated

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Blowout

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	600	Barrels			3	barrels
Brine						
Other					340	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/9/2015

Clean Up Concluded: 1/6/2014

Risk Evaluation:

None.

Areal Extent:

Approximately 1 BBL misted east off location to snow covered cropland; rest of fluid stayed on pad.

Potential Environmental Impacts:

None. Potential to impact topsoil avoided by mist staying on top of snow.

Action Taken or Planned:

Rick Hutchens with NDIC met with PH personnel onsite. Fluid on location will be removed by vac-truck to recycle. Mist covered snow will be removed and placed in a tank. Oil will be skimmed off and other fluids disposed of at an approved facility. Any contaminated surface material from pad will be hauled to an approved facility.

Wastes Disposal Location:

Agencies Involved: NDIC was notified at 6:21 a.m. NDDH was called at 10:13 a.m, left message.

Updates

Date: 1/2/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:50. 36 degrees F, overcast, south wind 5-15 mph. Observed site and took photos. While on location, cleanup crew was in the process of removing product from well pad. Area east of the lease road that had been impacted from the spray had been scraped with a blade. The soil was pushed up into a windrow approximately 75 feet long by 10 feet wide and 10 feet high. The area on the west side of the lease road showed considerable product on the vegetation and some soils, and it will need further cleanup. Cleanup operations were continuing, and further followup will be required to assess final cleanup of the site.

Date: 1/2/2015 **Status:** Reviewed - Follow-up Required

Author: Washek, Sandi

Updated Oil Volume: 600.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to blowout. Approximately 1 BBL misted east off location to snow-covered cropland; rest of fluid stayed on pad according to report. Followup needed.

Date: 1/14/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 1/14/2015.

Impacts still visible at site and somewhat beyond the lease location.

Followup in spring is necessary to ensure proper cleanup.

Date: 6/2/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 15:00 p.m. The weather was rainy, 61°F, with the wind from the northeast 10-15 mph. The road ditches of the lease road have been regraded and seeded. The field east of pad has been seeded, and the crop is growing. No further followup needed at this time. 47.93401; -102.96294